Exhibit 7.

Summary Forensic Examination of Residential Dwellings that Sustained Extensive Fire Damage in the Accident  $^{302}$ 

County Road 621 – Address	Structure Type	General Condition	Summarized Examination Observation(s)
# 4167	MH	fully consumed by fire (burned to the ground)	<ul> <li>substantial ground fire proximate to the structure</li> </ul>
			<ul> <li>found pieces of sheet metal from adjacent buildings</li> </ul>
# 4195	CWF	fully consumed by fire (burned to the ground)	<ul> <li>fatality (human remains) had been found inside, proximate to [sleeping] bed</li> </ul>
			<ul> <li>found several small O<sub>2</sub> tanks, electric space heater, LPG hot water heater, kerosene lamp, electric washer and dryer, LPG stove, portable television within rubble</li> </ul>
# 4201	MH	fully consumed by fire (burned to the ground)	<ul> <li>found LPG space heater, electric hot water heater within the rubble</li> </ul>
			<ul> <li>propane storage tank with fire damage at rear of the structure</li> </ul>
			<ul> <li>burnt-out automobile found adjacent to the structure</li> </ul>
# 4207	МН	fully consumed by fire (burned to the ground)	<ul> <li>fatality (human remains) had been found (outside) proximate to front door.</li> </ul>
			<ul> <li>found LPG stove, electric hot water heater, electric washer and dryer within the rubble</li> </ul>
			<ul> <li>forensic specimen recovered/examined (electrical power feed wire from hot water heater; see § 5.2.2)</li> </ul>
# 4207 shed*	CWF	fully consumed by fire (burned to the ground)	*note - apparent utility shed adjacent to the dwelling (as a part of the property)
			<ul> <li>found small LPG tank, battery charger, cooker, lawn mower, within the rubble</li> </ul>

<sup>302</sup> ref. § 5.2.1, as compiled by the Survival Factors Working Group participants

99

Nomenclature / abbreviations used in this Exhibit:

MH = mobile home / semi-permanently fixed in place

CWF conventional wood frame structure

LPG liquefied petroleum gas

-- End of this Exhibit --